

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problems Mailbox.**



09772561-080601




FIG. 1.




FIG. 2A.




FIG. 2B.




FIG. 2C.




FIG. 3.




FIG. 4.

09772561.080601






FIG. 8







Fig 10



09772561-080601

09772561-080601

Fig 11





[illegible]

Fig 14



09772561-080601

09772561-080601

Fig 15






Fig. ~~15~~ 16



0972561-080604


109772561.080601

Fig 17






Ends of Single member
with multiple
independently addressable
conductive regions




Ends of Two members each
with multiple independently
or non independently
addressable conductive
regions



Region can be a cut out
(filled with air) or a nonconductive
region

Ends of two members
each with multiple
non independtly
addressable conductive
regions



09772561-080601



Fig. 21





Fig 22



09772561-080601




Fig 23A




Fig 23D




Fig 23B




Fig 23E



Fig 23C




Fig 23F

09772564-080604
T09080 T95260